		Fluid Height on			Estimated Gallons of	Comments - Tank conditions / changing volumes after	Gallons and/or Tons	
<u>Tank ID</u>	Radius		-1	Tank Height	Liquid on May 2011	additional work	(bottoms in place)	
ast Tanks w/Activity under way on 9/2/2011				<u> </u>			-	
						SEE FOOTNOTE ON ESTIMATES; Fluid height is 1.5" at	x00 tons sludge on	
27	53.89	3.08	3.141592654	40	210,193	sidewalls; hard 10" heel at center (~419 bbls or 17,600 gallons) on 9/14/11.	9/15/11	CONTENTS PROFILED AND BEING REMOVED
21	33.63	3.08	3.141392034	40	210,193	Fluid height is 22'2-3/4" (36,112 bbls or 1,517,121 gallons vol) on		CONTENTS I NOTICED AND BEING REIVIOVED
26	53.89	7.41	3.141592654	40	505,692		sludge on 9/15/11	CONTENTS PROFILED AND BEING REMOVED
					initial estimate not	Removed 400,000 gal to Tank 26; Method to estimate volumes	~ 200 tons sludge on	
10	N/A	N/A	3.141592654	40	available	will be revised.	9/2/11	CONTENTS PROFILED AND BEING REMOVED
Larger Tanks NW of FM 2725 /Bishop Rd intersection								
						Removed 1850 bbls of water to Tank 7. On 8/15/11 moved appx	·	
2	25	7.25	3.141592654	24	106,480	350 bbls of water / emulsion to Tank 26	steel has been recycled. 280,653 gal liquid; sludge	DEMOLISHED
						Currently stands at appx 21'-4" (6682 bbls or 280,653 gallons) on		
7	23.66	7.5	3.141592654	32	98,660	8/15/11	floating roof.	
Tanks controlly located on the Definery site			0.1.1.200.200.1		33,333			
Tanks centrally located on the Refinery site						Currently ~ 10 inches (3400 bbls or 142,800 gal water w/residual	142.800 gallons water &	
30	85	3.5	3.141592654	N/A	594,234	TPH on top of water. Water should be clean.	residual TPH on bottom	
24	16.66	1	3.141592654	32	6,522	contains 2 to 3" (39 bbls)of water	1,637 gallons water	CONTENTS TO BE REMOVED AND DEMO SEPT 22
		_				` '		
20	16.66	32.16	3.141592654	32	209,758		40 tons caustic sludge	CONTENTS TO BE REMOVED AND DEMO SEPT 22
22	16.66	N/A	3.141592654	32		< 6' (39,000 gal or 931 bbls) water / rust-fltg roof on bottom; removed 210 bbl as wash water for Tank 27.	~30,000 gallons water	CONTENTS TO BE REMOVED AND DEMO SEPT 22
	10.00	IN/A	3.141372034	32		The second secon	0.5 to 1' rust w/collapsed	CONTENTS TO BE REIVIOVED AIVE DEIVIO SEI 1 22
23	16.66	0.29	3.141592654	32	1,891	holes in tank	roof	EMPTY AND READY FOR DEMO
					,	holes in tank quantities uncertain as man way difficult to		
19	16.66	N/A	3.141592654	32		remove	11 to 15 tons of solids	CONTENTS TO BE REMOVED AND DEMO SEPT 22
18	16.66	0.375	3.141592654	32	2,446	tank is rusty and contains holes	tank is empty	EMPTY AND READY FOR DEMO
21	16.66	4.5	3.141592654	32	29,350		3" to 4" of rust & sediment	EMPTY AND READY FOR DEMO
17	16.66	1	3.141592654	32	6,522	1.5" (19 bbl or 815 gal) of sludge	4 tons sludge	CONTENTS TO BE REMOVED AND DEMO SEPT 22
Small Tank South of Tanks 17 - 24 activity on 9/2/2011					-			
311aii 1aiii 30acii 01 1aiii 317 24 accivity 011 3/2/2011							assume 12" of solids (10	
Y1	9.5	6	3.141592654	10.25	12,725		tons)	
Small Tanks NW of Tanks 17-24								
<u> </u>							assume 12"of solids (5	
n2	6	5	3.141592654	15.41	4,230	could not gauge, fluid level based on audio	tons)	
							assume 12"of solids (5	
n1	6	15	3.141592654	15.41	12,690	could not gauge, fluid level based on audio	tons)	
Small Tanks NW of FM 2725 /Bishop Rd intersection								
						BS&W - Tank tops will be removed to 3' from ground surface on		
X1	9	2	3.141592654	21	3,807	9/16/2011	tons)	CONTENTS TO BE REMOVED AND DEMO SEPT 16 & 19
Va	_		2.4.44502055	24	2.007	BS&W - Tank tops will be removed to 3' from ground surface on 9/16/2011	•	CONTENTS TO BE DEMOVED AND DEMO SERT 16 9 10
X2	9	2	3.141592654	21	3,807	BS&W is 2" to 3" sludge (240 gal or 5.7 bbl); top was removed;	tons)	CONTENTS TO BE REMOVED AND DEMO SEPT 16 & 19
X3	7	2	3.141592654	16	2,303	3" wall to floor remain.	1 ton on floor; 9/15/11	DEMOLISHED
	,	_	5.2.232334				, , ,	
			Total G	allons	1,801,393.52	Tanks X1, X2, and X3 not in total because the liquid is BS&W		
Superior Oil Tanks								
	_	Empty		40		Tank has a new bottom and being repaired by Superior		
		?? Empty		48 48		Has been repaired by Superior Currently empty with manway off tank.		
	<u> </u>	LITIPLY		40		carreinty empty with manway on tank.		
Notes								
red - tank has been demolished.								
blue - tank is empty / ready to be demolished.								
green - tank contents are profiled or being removed.								
violet - tanks are scheduled for shearing / removal of co								
orange - tanks are scheduled for shearing / removal of c	ontents or	n week of Sept 22	2, 2011					
Currently the fluid height is 1.5" at sidewalls: Thoro	exists a h	 nard 10" heel at	the center Th	e assumnti	 nn is 7 loads remain @	70bbls /load (490 bbls or 20,000 gallons) on 9/16/11. The		
at sidewalls, There	CNISCS & I	iara 10 HEEL AL	and deliter. III	c assumption	orris / Iodus (Ellidili @	7.00013 / 1000 (400 0013 01 20,000 gailolis) 011 3/ 10/ 11. THE		